



Investigation Information:	
Upstream Input: (L/S, P/S) N/A	
Upstream Manhole: MR28	
Downstream Manhole: MR30	
Depth of Flow: 8.5"	
Description of Site Hydraulics:	
No abnormal conditions were observed.	
Manhole Information:	
Manhole Depth: 14'7"	
Manhole Material / Condition:	
Brick / Good	
Active Drop Connections?	
No	
System Character:	
X	Residential
	Commercial
	Industrial
Notes:	
Legend:	
	Cast Iron Flap Valve
	Sensor Location
N.T.S.- Not to scale	

The monitoring period ended as of February 28, 2005.