

Sheet 14 **Surveyor's Name** Roy Bass **Certificate Number** U-316-07003375 **Date** 20250717
System Owner **Survey Customer** **Time** 11:50
Drainage Area **Locality/City Name** Tulsa
P.O. No **Location (No. & Name)** 13308 E 32nd Pl
Further Location Details **Inspection Level** Level 2
Outgoing Rim to Invert 7.7 ft **Outgoing Grade to Invert** 7.7 ft **Rim to Grade** 0.0 ft
Use of Sewer Sanitary **Year Laid** **Year Rehabilitated** **Media Label**
Purpose Sewer System Evaluation Survey **Sewer Category**
Pre-Cleaning No Pre-Cleaning **Date Cleaned** **Weather**
Location Code Yard **Potential for Runoff** **Evidence of Surcharge** No
Access Point Type Manhole **Coordinate System**
Northing **Easting** **Elevation** **Accuracy of GPS**
Inspection Status Remote Inspection
Additional Information No chimney, channel is VCP
Node Surface Types

Concrete Pavement ☐ **Concrete Collar** ☐ **Asphalt** ☐ **Grass / Dirt** ☒ **Gravel** ☐ **Other** ☐

Cover

Cover Shape Circular **Cover Bearing Surface Diameter Width**
Cover Size 23.3 in **Cover Bearing Surface Diameter** 23.0 in
Cover Size Width **# Vent Holes**
Cover Material Cast Iron **Vent Hole Diameter**
Cover Frame Fit Good
Cover Type

<input checked="" type="checkbox"/> Solid	<input type="checkbox"/> Bolted
<input type="checkbox"/> Vented/Slots	<input type="checkbox"/> Locking
<input type="checkbox"/> Gasketed	<input type="checkbox"/> Lamphole
<input type="checkbox"/> Hatch Single	<input type="checkbox"/> Inner Cover
<input type="checkbox"/> Hatch Double	

Cover Condition

<input checked="" type="checkbox"/> Solid	<input type="checkbox"/> Missing
<input type="checkbox"/> Cracked	<input type="checkbox"/> Corroded/Pitted
<input type="checkbox"/> Broken	<input type="checkbox"/> Bolts Missing
<input type="checkbox"/> Restraint Missing	
<input type="checkbox"/> Restraint Defective	

Cover Insert

Cover Insert Type None

Cover Insert Condition

<input type="checkbox"/> Solid	<input type="checkbox"/> Leaking
<input type="checkbox"/> Poorly Fitting	<input type="checkbox"/> Corroded
<input type="checkbox"/> Cracked/Torn/Holes	<input type="checkbox"/> Insert Fell

Sheet 14

Survey Date 20250717

P.O. No

Location (No. & Name) 13308 E 32nd Pl

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

Adjustment Ring Condition

<input type="checkbox"/> Sound	<input type="checkbox"/> Corroded/Pitted/Worn
<input type="checkbox"/> Cracked	<input type="checkbox"/> Leaking
<input type="checkbox"/> Broken	<input type="checkbox"/> Poor Installation

Frame

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.0 in

Frame Seal Inflow None

Frame Clear Opening Diameter 21.8 in

Frame Condition

<input checked="" type="checkbox"/> Sound	<input type="checkbox"/> Missing
<input type="checkbox"/> Cracked	<input type="checkbox"/> Corroded/Pitted/Worn
<input type="checkbox"/> Broken	<input type="checkbox"/> Coated

Frame Seal Condition

<input checked="" type="checkbox"/> Sound	<input type="checkbox"/> Loose/Not Attached
<input type="checkbox"/> Cracked	
<input type="checkbox"/> Broken	<input type="checkbox"/> Offset

Chimney

Chimney Material 1 Brick

Interior Chimney Coating/Liner Cementitious

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 1.4 in

Cone

Cone Type Conical centered

Cone Depth 3.7 in

Exterior Cone Coating/Liner

Cone Material Brick

Interior Cone Coating/Liner

Wall

Wall Diameter 1 48

Wall Depth 7.1 in

Wall Diameter 2

Interior Wall Coating/Liner Cementitious

Wall Material Brick

Exterior Wall Coating/Liner

Bench

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material	Concrete (non-reinforced)
Channel Type	Concrete (non-reinforced)
Channel Exposure	F
Channel Installed	Y

Step

# Steps	4
Step Material	Metal

Sheet 14

Survey Date 20250717

P.O. No

Location (No. & Name) 13308 E 32nd Pl

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Pipe Connections

Num	Clk	Rim to Pos	Invert	Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special Condition	PSR
1	6	7.7		O	VCP	C	8		D	S	GR	Auto Pipe 26
	Mainline		Comments									
2	12	3.8		I	PVC	C	8		S	D	IU	Auto Pipe 27
	Mainline		Comments									
3	12	7.5		I	PVC	C	8		S	S	IL	Auto Pipe 28
	Mainline		Comments									

Observations

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
1.0 ft		CMI	LFZ						12	12	360-0.0
	Remarks		Lining material deteriorated, blocks visible								
2.7 ft		COI	LFDL						12	12	360-0.0
	Remarks		Repeating defect								
2.7 ft		COI	LFZ						12	12	360-0.0
	Remarks		Exposed block								
2.9 ft		COI	DAR			10			3	4	360-0.0
	Remarks										
3.1 ft		COI	IR						9	10	360-0.0
	Remarks										
3.1 ft		COI	IR						12		360-0.0
	Remarks		Pipe seal								
3.1 ft		COI	IS						12		360-0.0
	Remarks		Pipe seal								
3.1 ft		WI	LFDL	S01					12	12	360-0.0
	Remarks										
3.7 ft		WI	LFZ	S02					12	12	360-0.0
	Remarks		Exposed block								
4.5 ft		WI	VC								360-0.0
	Remarks										
5.6 ft		WI	DAR			10			3	4	360-0.0
	Remarks										
6.4 ft		WI	CC						3	7	360-0.0
	Remarks										
6.4 ft		WI	FC						7	11	360-0.0
	Remarks										
6.4 ft		WI	ID						11		360-0.0
	Remarks										
6.4 ft		WI	IR						9		360-0.0
	Remarks										

Sheet 14

Survey Date 20250717

P.O. No

Location (No. & Name) 13308 E 32nd Pl

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

6.4 ft		WI	IR							5	7	360-0.0
	Remarks											
6.4 ft		WI	IS							8	11	360-0.0
	Remarks											
7.1 ft		B	DSZ				10			12	12	360-0.0
	Remarks		Debris from drop pipe									
7.1 ft		WI	LFDL	F01						12	12	360-0.0
	Remarks											
7.1 ft		WI	LFZ	F02						12	12	360-0.0
	Remarks		Exposed block									