

Sheet 1355 Surveyor's Name Roy Bass

Certificate Number U-316-07003375

Date 20250826

System Owner

Survey Customer

Time 14:10

Drainage Area

Locality/City Name Tulsa

P.O. No

Location (No. &amp; Name) 3623 S 131st E Ave

Further Location Details

Inspection Level Level 2

Outgoing Rim to Invert 7.7 ft

Outgoing Grade to Invert 7.6 ft

Rim to Grade 0.1 ft

Use of Sewer Sanitary

Year Laid

Year Rehabilitated

Media Label

Purpose Sewer System Evaluation Survey

Sewer Category

Pre-Cleaning No Pre-Cleaning

Date Cleaned

Weather

Location Code Yard

Potential for Runoff

Evidence of Surcharge Yes

Access Point Type Manhole

Coordinate System

Northing

Easting

Elevation

Accuracy of GPS

Inspection Status Remote Inspection

Additional Information Lining material cracked at frame seal, seal is defective

Node Surface Types

Concrete Pavement ☐Concrete Collar ☐Asphalt ☐Grass / Dirt ☒Gravel ☐Other ☐**Cover**

Cover Shape Circular

Cover Bearing Surface Diameter Width

Cover Size 23.8 in

Cover Bearing Surface Diameter 23.5 in

Civer Size Width

# Vent Holes

Cover Material Cast Iron

Vent Hole Diameter

Cover Frame Fit Good

Cover Type

- |   |                                      |
|---|--------------------------------------|
| <input checked="" type="checkbox"/> Solid | <input type="checkbox"/> Bolted      |
| <input type="checkbox"/> Vented/Slots     | <input type="checkbox"/> Locking     |
| <input type="checkbox"/> Gasketed         | <input type="checkbox"/> Lamphole    |
| <input type="checkbox"/> Hatch Single     | <input type="checkbox"/> Inner Cover |
| <input type="checkbox"/> Hatch Double     |                                      |

Cover Condition

- |  |  |
|--|--|
| <input checked="" type="checkbox"/> Solid    | <input type="checkbox"/> Missing         |
| <input type="checkbox"/> Cracked             | <input type="checkbox"/> Corroded/Pitted |
| <input type="checkbox"/> Broken              | <input type="checkbox"/> Bolts Missing   |
| <input type="checkbox"/> Restraint Missing   |  |
| <input type="checkbox"/> Restraint Defective |  |

**Cover Insert**

Cover Insert Type None

Cover Insert Condition

- |   |                                      |
|---|--------------------------------------|
| <input type="checkbox"/> Solid              | <input type="checkbox"/> Leaking     |
| <input type="checkbox"/> Poorly Fitting     | <input type="checkbox"/> Corroded    |
| <input type="checkbox"/> Cracked/Torn/Holes | <input type="checkbox"/> Insert Fell |

Sheet 1355

Survey Date 20250826

P.O. No

Location (No. &amp; Name) 3623 S 131st E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

**Adjustment Ring Condition**

- |                                  |   |
|----------------------------------|---|
| <input type="checkbox"/> Sound   | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking              |
| <input type="checkbox"/> Broken  | <input type="checkbox"/> Poor Installation    |

**Frame**

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.0 in

Frame Seal Inflow Infil Stained

Frame Clear Opening Diameter 22.5 in

**Frame Condition**

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Missing              |
| <input type="checkbox"/> Cracked          | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken           | <input type="checkbox"/> Coated               |

**Frame Seal Condition**

- |   |   |
|---|---|
| <input type="checkbox"/> Sound              | <input type="checkbox"/> Loose/Not Attached |
| <input checked="" type="checkbox"/> Cracked |   |
| <input type="checkbox"/> Broken             | <input type="checkbox"/> Offset             |

**Chimney**

Chimney Material 1 Brick

Interior Chimney Coating/Liner Cementitious

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 1.4 in

**Cone**

Cone Type Conical centered

Cone Depth 3.9 in

Exterior Cone Coating/Liner

Cone Material Brick

Interior Cone Coating/Liner

**Wall**

Wall Diameter 1 48

Wall Depth 7.3 in

Wall Diameter 2

Interior Wall Coating/Liner Cementitious

Wall Material Brick

Exterior Wall Coating/Liner

**Bench**

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

**Channel/Step****Channel**

Channel Material Concrete (non-reinforced)

Channel Type Concrete (non-reinforced)

Channel Exposure F

Channel Installed Y

**Step**

# Steps 4

Step Material Plastic

Sheet 1355

Survey Date 20250826

P.O. No

Location (No. &amp; Name) 3623 S 131st E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	7.7	O	VCP	C	8		S	D	GR	Auto Pipe 2813
	Mainline		Comments								
2	1	7.7	I	VCP	C	8		S	S	GR	Auto Pipe 2814
	Mainline		Comments								

**Observations**

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
5.9 ft	WI	DAR				10			2		360-0.0
	Remarks										
7.3 ft	B	DSZ				10			12	12	360-0.0
	Remarks		Surcharge evidence								
7.3 ft	B	SRI							12	12	360-0.0
	Remarks										