

Sheet 1244	Surveyor's Name Caleb Lyda	Certificate Number P0053047-032025	Date 20250312
System Owner		Survey Customer	Time 09:43
Drainage Area		Locality/City Name Tulsa	
P.O. No		Location (No. & Name) 13518 E 36th St	
Further Location Details		Inspection Level Level 2	
Outgoing Rim to Invert 6.8 ft	Outgoing Grade to Invert 6.3 ft	Rim to Grade 0.5 ft	
Use of Sewer Sanitary	Year Laid	Year Rehabilitated	Media Label
Purpose Sewer System Evaluation Survey		Sewer Category	
Pre-Cleaning No Pre-Cleaning	Date Cleaned	Weather	
Location Code Yard	Potential for Runoff	Evidence of Surcharge No	
Access Point Type Other Special Chamber		Coordinate System	
Northing	Easting	Elevation	Accuracy of GPS
Inspection Status Remote Inspection			
Additional Information	No chimney, no cone, no bench, channel is VCP, manhole cover has restraints that make the cover wobble		

Node Surface Types

Concrete Pavement <input type="checkbox"/>	Concrete Collar <input type="checkbox"/>	Asphalt <input type="checkbox"/>	Grass / Dirt <input checked="" type="checkbox"/>	Gravel <input type="checkbox"/>	Other <input type="checkbox"/>
--	--	----------------------------------	--	---------------------------------	--------------------------------

Cover

Cover Shape	Circular	Cover Bearing Surface Diameter Width	
Cover Size	11.3 in	Cover Bearing Surface Diameter	11.0 in
Cover Size Width		# Vent Holes	1
Cover Material	Cast Iron	Vent Hole Diameter	
Cover Frame Fit	Rocks/Wobbles	> 1/2 inch (13mm) <= 1 inch (25mm)	
Cover Type			
<input type="checkbox"/> Solid	<input type="checkbox"/> Bolted	<input checked="" type="checkbox"/> Solid	<input type="checkbox"/> Missing
<input checked="" type="checkbox"/> Vented/Slots	<input type="checkbox"/> Locking	<input type="checkbox"/> Cracked	<input type="checkbox"/> Corroded/Pitted
<input type="checkbox"/> Gasketed	<input checked="" type="checkbox"/> Lamphole	<input type="checkbox"/> Broken	<input type="checkbox"/> Bolts Missing
<input type="checkbox"/> Hatch Single	<input type="checkbox"/> Inner Cover	<input type="checkbox"/> Restraint Missing	
<input type="checkbox"/> Hatch Double		<input type="checkbox"/> Restraint Defective	

Cover Insert

Cover Insert Type None

Cover Insert Condition

<input type="checkbox"/> Solid	<input type="checkbox"/> Leaking
<input type="checkbox"/> Poorly Fitting	<input type="checkbox"/> Corroded
<input type="checkbox"/> Cracked/Torn/Holes	<input type="checkbox"/> Insert Fell

Sheet 1244

Survey Date 20250312

P.O. No

Location (No. & Name) 13518 E 36th St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

Adjustment Ring Condition

<input type="checkbox"/> Sound	<input type="checkbox"/> Corroded/Pitted/Worn
<input type="checkbox"/> Cracked	<input type="checkbox"/> Leaking
<input type="checkbox"/> Broken	<input type="checkbox"/> Poor Installation

Frame

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 1.3 in

Frame Depth

Frame Bearing Surface Depth 0.5 in

Frame Seal Inflow None

Frame Clear Opening Diameter 9.5 in

Frame Condition

<input type="checkbox"/> Sound	<input type="checkbox"/> Missing
<input type="checkbox"/> Cracked	<input type="checkbox"/> Corroded/Pitted/Worn
<input type="checkbox"/> Broken	<input checked="" type="checkbox"/> Coated

Frame Seal Condition

<input type="checkbox"/> Sound	<input type="checkbox"/> Loose/Not Attached
<input checked="" type="checkbox"/> Cracked	
<input type="checkbox"/> Broken	<input type="checkbox"/> Offset

Chimney

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

Cone

Cone Type Flattop

Cone Depth 0.0 in

Exterior Cone Coating/Liner

Cone Material Other

Interior Cone Coating/Liner

Wall

Wall Diameter 1 8

Wall Depth 6.8 in

Wall Diameter 2

Interior Wall Coating/Liner None - No Coating

Wall Material Vitrified Clay

Exterior Wall Coating/Liner

Bench

Bench Present N

Bench Material Other

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material	Other
Channel Type	Other
Channel Exposure	F
Channel Installed	Y

Step

# Steps	0
Step Material	

Sheet 1244

Survey Date 20250312

P.O. No

Location (No. & Name) 13518 E 36th St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Pipe Connections

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	6.8	O	VCP	C	8	8	S	S	GR	080-0679:080-0678
	Mainline		Comments								

Observations

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
0.5 ft	WI	IS							9		360-0.0
	Remarks										
4.6 ft	WI	VZ					1				360-0.0
	Remarks		Spider								
5.2 ft	WI	MGO									360-0.0
	Remarks		Appears to be like a calcium build up, unable to verify								