

Sheet 1431 Surveyor's Name BK

Certificate Number U-218-070300218

Date 20251208

System Owner

Survey Customer

Time 13:51

Drainage Area

Locality/City Name Tulsa

P.O. No

Location (No. &amp; Name) 1543 S 122nd E Ave

Further Location Details

Inspection Level Level 2

Outgoing Rim to Invert 5.1 ft

Outgoing Grade to Invert 5.1 ft

Rim to Grade 0.0 ft

Use of Sewer Sanitary

Year Laid

Year Rehabilitated

Media Label

Purpose Sewer System Evaluation Survey

Sewer Category

Pre-Cleaning No Pre-Cleaning

Date Cleaned

Weather

Location Code Yard

Potential for Runoff

Evidence of Surcharge No

Access Point Type Other Special Chamber

Coordinate System

Northing

Easting

Elevation

Accuracy of GPS

Inspection Status Remote Inspection

Additional Information Lamphole - No chimney, no cone, no bench, channel is VCP

Node Surface Types

Concrete Pavement ☐Concrete Collar ☐Asphalt ☐Grass / Dirt ☒Gravel ☐Other ☐**Cover**

Cover Shape Circular

Cover Bearing Surface Diameter Width

Cover Size 11.3 in

Cover Bearing Surface Diameter 11.0 in

Civer Size Width

# Vent Holes

Cover Material Cast Iron

Vent Hole Diameter

Cover Frame Fit Good

Cover Type

- |   |  |
|---|--|
| <input checked="" type="checkbox"/> Solid | <input type="checkbox"/> Bolted              |
| <input type="checkbox"/> Vented/Slots     | <input type="checkbox"/> Locking             |
| <input type="checkbox"/> Gasketed         | <input checked="" type="checkbox"/> Lamphole |
| <input type="checkbox"/> Hatch Single     | <input type="checkbox"/> Inner Cover         |
| <input type="checkbox"/> Hatch Double     |  |

Cover Condition

- |  |  |
|--|--|
| <input checked="" type="checkbox"/> Solid    | <input type="checkbox"/> Missing         |
| <input type="checkbox"/> Cracked             | <input type="checkbox"/> Corroded/Pitted |
| <input type="checkbox"/> Broken              | <input type="checkbox"/> Bolts Missing   |
| <input type="checkbox"/> Restraint Missing   |  |
| <input type="checkbox"/> Restraint Defective |  |

**Cover Insert**

Cover Insert Type None

Cover Insert Condition

- |   |                                      |
|---|--------------------------------------|
| <input type="checkbox"/> Solid              | <input type="checkbox"/> Leaking     |
| <input type="checkbox"/> Poorly Fitting     | <input type="checkbox"/> Corroded    |
| <input type="checkbox"/> Cracked/Torn/Holes | <input type="checkbox"/> Insert Fell |

Sheet 1431

Survey Date 20251208

P.O. No

Location (No. &amp; Name) 1543 S 122nd E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

**Adjustment Ring Condition**☐ Sound☐ Corroded/Pitted/Worn☐ Cracked☐ Leaking☐ Broken☐ Poor Installation**Frame**

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.5 in

Frame Depth

Frame Bearing Surface Depth 1.3 in

Frame Seal Inflow None

Frame Clear Opening Diameter 9.5 in

**Frame Condition**☒ Sound☐ Missing☐ Cracked☐ Corroded/Pitted/Worn☐ Broken☐ Coated**Frame Seal Condition**☒ Sound☐ Loose/Not Attached☐ Cracked☐ Broken☐ Offset**Chimney**

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

**Cone**

Cone Type Conical centered

Cone Depth 0.0 in

Exterior Cone Coating/Liner

Cone Material Other

Interior Cone Coating/Liner

**Wall**

Wall Diameter 1 8

Wall Depth 4.3 in

Wall Diameter 2

Interior Wall Coating/Liner None - No Coating

Wall Material Vitrified Clay

Exterior Wall Coating/Liner

**Bench**

Bench Present N

Bench Material

Bench Coating/Liner Bench Liner

**Channel/Step****Channel**

Channel Material Other

Channel Type Other

Channel Exposure F

Channel Installed Y

**Step**

# Steps 0

Step Material

Sheet 1431

Survey Date 20251208

P.O. No

Location (No. &amp; Name) 1543 S 122nd E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	5.1	O	VCP	C	8		D	S	GR	Auto Pipe 44AA
	Mainline		Comments								

**Observations**

Distance	Comp	Code	CD	Jnt	Stp	%	In1	In2	Fr	To	Video Reference
0.9 ft	WI	DAZ				5			12	12	
	Remarks	Surcharge evidence									
3.1 ft	WI	VZ					0.3				
	Remarks	Gnats									
3.2 ft	WI	FC							12	12	
	Remarks										
3.2 ft	WI	ISSR				5			6	2	
	Remarks	H									