

Sheet 483      **Surveyor's Name** Brian Kauppenin      **Certificate Number** U-218-070300218      **Date** 20250208  
**System Owner**      **Survey Customer**      **Time** 11:32  
**Drainage Area**      **Locality/City Name** Tulsa  
**P.O. No**      **Location (No. & Name)** 2203 S 133rd E Ave  
**Further Location Details**      **Inspection Level** Level 2  
**Outgoing Rim to Invert** 6.3 ft      **Outgoing Grade to Invert** 6.3 ft      **Rim to Grade** 0.0 ft  
**Use of Sewer** Sanitary      **Year Laid**      **Year Rehabilitated**      **Media Label**  
**Purpose** Sewer System Evaluation Survey      **Sewer Category**  
**Pre-Cleaning** No Pre-Cleaning      **Date Cleaned**      **Weather**  
**Location Code** Yard      **Potential for Runoff**      **Evidence of Surcharge** Yes  
**Access Point Type** Manhole      **Coordinate System**  
**Northing**      **Easting**      **Elevation**      **Accuracy of GPS**  
**Inspection Status** Remote Inspection  
**Additional Information** No chimney  
**Node Surface Types**

**Concrete Pavement** ☐      **Concrete Collar** ☐      **Asphalt** ☐      **Grass / Dirt** ☒      **Gravel** ☐      **Other** ☐

**Cover**

**Cover Shape** Circular      **Cover Bearing Surface Diameter Width**  
**Cover Size** 23.3 in      **Cover Bearing Surface Diameter** 23.0 in  
**Civer Size Width**      **# Vent Holes**  
**Cover Material** Cast Iron      **Vent Hole Diameter**  
**Cover Frame Fit** Good

**Cover Type**

☒ **Solid**      ☐ **Bolted**  
☐ **Vented/Slots**      ☐ **Locking**  
☐ **Gasketed**      ☐ **Lamphole**  
☐ **Hatch Single**      ☐ **Inner Cover**  
☐ **Hatch Double**

**Cover Condition**

☒ **Solid**      ☐ **Missing**  
☐ **Cracked**      ☐ **Corroded/Pitted**  
☐ **Broken**      ☐ **Bolts Missing**  
☐ **Restraint Missing**  
☐ **Restraint Defective**

**Cover Insert**

**Cover Insert Type** None

**Cover Insert Condition**

☐ **Solid**      ☐ **Leaking**  
☐ **Poorly Fitting**      ☐ **Corroded**  
☐ **Cracked/Torn/Holes**      ☐ **Insert Fell**

Sheet 483

Survey Date 20250208

P.O. No

Location (No. &amp; Name) 2203 S 133rd E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

**Adjustment Ring Type** Solid  
**Adjustment Ring Material** Cast Iron  
**Adjustment Ring Height**

**Adjustment Ring Condition**

☒ **Sound** ☐ **Corroded/Pitted/Worn**  
☐ **Cracked** ☐ **Leaking**  
☐ **Broken** ☐ **Poor Installation**

**Frame**

**Frame Material** Cast Iron  
**Frame Bearing Surface Width** 0.8 in  
**Frame Bearing Surface Depth** 1.0 in  
**Frame Clear Opening Diameter** 21.8 in

**Frame Offset Distance** 0.0 in**Frame Depth****Frame Seal Inflow** None**Frame Condition**

☒ **Sound** ☐ **Missing**  
☐ **Cracked** ☐ **Corroded/Pitted/Worn**  
☐ **Broken** ☐ **Coated**

**Frame Seal Condition**

☒ **Sound** ☐ **Loose/Not Attached**  
☐ **Cracked**  
☐ **Broken** ☐ **Offset**

**Chimney**

**Chimney Material 1** Other  
**Chimney Material 2**  
**Chimney Clear Opening**  
**Chimney Depth** 0.0 in

**Interior Chimney Coating/Liner** None - No Coating**Exterior Chimney Coating/Liner****Chimney I/I****Cone**

**Cone Type** Conical centered  
**Exterior Cone Coating/Liner**  
**Interior Cone Coating/Liner**

**Cone Depth** 4.0 in**Cone Material** Brick**Wall**

**Wall Diameter 1** 48  
**Wall Diameter 2**  
**Wall Material** Brick

**Wall Depth** 5.8 in**Interior Wall Coating/Liner** Cementitious**Exterior Wall Coating/Liner****Bench**

**Bench Present** Y  
**Bench Material** Concrete (non-reinforced)  
**Bench Coating/Liner** Bench Liner

**Channel/Step****Channel**

**Channel Material** Concrete (non-reinforced)  
**Channel Type** Concrete (non-reinforced)  
**Channel Exposure** F  
**Channel Installed** Y

**Step**

**# Steps** 2  
**Step Material** Plastic

Sheet 483

Survey Date 20250208

P.O. No

Location (No. &amp; Name) 2203 S 133rd E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

Num	Clk Rim to		Direc	Material	Shape	Diam	Width	Pipe Cond	Seal Cond	Special	
	Pos	Invert								Condition	PSR
1	6	6.3	O	VCP	C	8		D	S	GR	Auto Pipe 327C
	Mainline			Comments							