

|  |                                 |                                       |                 |
|--|---------------------------------|---------------------------------------|-----------------|
| Sheet 11                               | Surveyor's Name Roy Bass        | Certificate Number U-316-07003375     | Date 20250624   |
| System Owner                           |                                 | Survey Customer                       | Time 13:39      |
| Drainage Area                          |                                 | Locality/City Name Tulsa              |                 |
| P.O. No                                |                                 | Location (No. & Name) 12101 E 25th St |                 |
| Further Location Details               |                                 | Inspection Level Level 2              |                 |
| Outgoing Rim to Invert 7.3 ft          | Outgoing Grade to Invert 7.3 ft | Rim to Grade 0.0 ft                   |                 |
| Use of Sewer Sanitary                  | Year Laid                       | Year Rehabilitated                    | Media Label     |
| Purpose Sewer System Evaluation Survey |                                 | Sewer Category                        |                 |
| Pre-Cleaning No Pre-Cleaning           | Date Cleaned                    | Weather                               |                 |
| Location Code Yard                     | Potential for Runoff            | Evidence of Surcharge No              |                 |
| Access Point Type Manhole              |                                 | Coordinate System                     |                 |
| Northing                               | Easting                         | Elevation                             | Accuracy of GPS |
| Inspection Status Remote Inspection    |                                 |                                       |                 |
| Additional Information                 |                                 |                                       |                 |
| Node Surface Types                     |                                 |                                       |                 |

|                   |                          |                 |                          |         |                          |              |                                     |        |                          |       |                          |
|-------------------|--------------------------|-----------------|--------------------------|---------|--------------------------|--------------|-------------------------------------|--------|--------------------------|-------|--------------------------|
| Concrete Pavement | <input type="checkbox"/> | Concrete Collar | <input type="checkbox"/> | Asphalt | <input type="checkbox"/> | Grass / Dirt | <input checked="" type="checkbox"/> | Gravel | <input type="checkbox"/> | Other | <input type="checkbox"/> |
|-------------------|--------------------------|-----------------|--------------------------|---------|--------------------------|--------------|-------------------------------------|--------|--------------------------|-------|--------------------------|

**Cover**

|   |                                      |  |  |
|---|--------------------------------------|--|--|
| Cover Shape                               | Circular                             | Cover Bearing Surface Diameter Width         |  |
| Cover Size                                | 23.3 in                              | Cover Bearing Surface Diameter               | 23.0 in                                  |
| Civer Size Width                          |                                      | # Vent Holes                                 |  |
| Cover Material                            | Cast Iron                            | Vent Hole Diameter                           |  |
| Cover Frame Fit                           | Good                                 |  |  |
| Cover Type                                |                                      | Cover Condition                              |  |
| <input checked="" type="checkbox"/> Solid | <input type="checkbox"/> Bolted      | <input checked="" type="checkbox"/> Solid    | <input type="checkbox"/> Missing         |
| <input type="checkbox"/> Vented/Slots     | <input type="checkbox"/> Locking     | <input type="checkbox"/> Cracked             | <input type="checkbox"/> Corroded/Pitted |
| <input type="checkbox"/> Gasketed         | <input type="checkbox"/> Lamphole    | <input type="checkbox"/> Broken              | <input type="checkbox"/> Bolts Missing   |
| <input type="checkbox"/> Hatch Single     | <input type="checkbox"/> Inner Cover | <input type="checkbox"/> Restraint Missing   |  |
| <input type="checkbox"/> Hatch Double     |                                      | <input type="checkbox"/> Restraint Defective |  |

**Cover Insert**

|                   |      |
|-------------------|------|
| Cover Insert Type | None |
|-------------------|------|

**Cover Insert Condition**

|   |                                      |
|---|--------------------------------------|
| <input type="checkbox"/> Solid              | <input type="checkbox"/> Leaking     |
| <input type="checkbox"/> Poorly Fitting     | <input type="checkbox"/> Corroded    |
| <input type="checkbox"/> Cracked/Torn/Holes | <input type="checkbox"/> Insert Fell |

Sheet 11

Survey Date 20250624

P.O. No

Location (No. &amp; Name) 12101 E 25th St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Adj. Ring**

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

**Adjustment Ring Condition**

- |                                  |   |
|----------------------------------|---|
| <input type="checkbox"/> Sound   | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking              |
| <input type="checkbox"/> Broken  | <input type="checkbox"/> Poor Installation    |

**Frame**

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.0 in

Frame Seal Inflow None

Frame Clear Opening Diameter 21.8 in

**Frame Condition**

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Missing              |
| <input type="checkbox"/> Cracked          | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken           | <input type="checkbox"/> Coated               |

**Frame Seal Condition**

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Loose/Not Attached |
| <input type="checkbox"/> Cracked          |   |
| <input type="checkbox"/> Broken           | <input type="checkbox"/> Offset             |

**Chimney**

Chimney Material 1 Brick

Interior Chimney Coating/Liner Cementitious

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 1.1 in

**Cone**

Cone Type Conical centered

Cone Depth 3.0 in

Exterior Cone Coating/Liner

Cone Material Brick

Interior Cone Coating/Liner

**Wall**

Wall Diameter 1 48

Wall Depth 6.7 in

Wall Diameter 2

Interior Wall Coating/Liner Cementitious

Wall Material Brick

Exterior Wall Coating/Liner

**Bench**

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

**Channel/Step****Channel**

Channel Material Concrete (non-reinforced)

Channel Type Concrete (non-reinforced)

Channel Exposure F

Channel Installed Y

**Step**

# Steps 4

Step Material Plastic

Sheet 11

Survey Date 20250624

P.O. No

Location (No. &amp; Name) 12101 E 25th St

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

**Pipe Connections**

| Num | Clk      | Rim to Pos | Invert   | Direc | Material | Shape | Diam | Width | Pipe Cond | Seal Cond | Special Condition | PSR          |
|-----|----------|------------|----------|-------|----------|-------|------|-------|-----------|-----------|-------------------|--------------|
| 1   | 6        | 7.3        |          | O     | VCP      | C     | 8    |       | D         | S         | GR                | Auto Pipe 20 |
|     | Mainline |            | Comments |       |          |       |      |       |           |           |                   |              |
| 2   | 12       | 7.2        |          | I     | PE       | C     | 8    |       | S         | S         | GR                | Auto Pipe 21 |
|     | Mainline |            | Comments |       |          |       |      |       |           |           |                   |              |

**Observations**

| Distance | Comp   | Code | CD | Jnt | Stp | %  | In1 | In2 | Fr | To | Video Reference |
|----------|--|------|----|-----|-----|----|-----|-----|----|----|-----------------|
| 1.2 ft   | COI  | CC   |    |     |     |    |     |     | 11 | 12 | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 1.2 ft   | COI  | FC   |    |     |     |    |     |     | 3  | 4  | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 1.2 ft   | COI  | IS   |    |     |     |    |     |     | 3  | 4  | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 1.2 ft   | COI  | IS   |    |     |     |    |     |     | 11 | 12 | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 2.2 ft   | COI  | LFDL |    |     |     |    |     |     | 12 | 1  | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 3.1 ft   | WI   | VC   |    |     |     |    |     |     |    |    | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 3.2 ft   | WI   | DAR  |    |     |     | 5  |     |     | 8  |    | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 4.0 ft   | WI   | MGO  |    |     |     |    |     |     |    |    | 360-0.0         |
|          | Remarks 8:00, rusty object, possible remnant of old step |      |    |     |     |    |     |     |    |    |                 |
| 4.4 ft   | WI   | IS   |    |     |     |    |     |     | 8  |    | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 6.7 ft   | B  | DSC  |    |     |     | 10 |     |     | 12 | 1  | 360-0.0         |
|          | Remarks  |      |    |     |     |    |     |     |    |    |                 |
| 7.1 ft   | C  | DSZ  |    |     |     | 5  |     |     | 11 |    | 360-0.0         |
|          | Remarks Quarter  |      |    |     |     |    |     |     |    |    |                 |