

Sheet 487 **Surveyor's Name** Brian Kauppenin **Certificate Number** U-218-070300218 **Date** 20250210
System Owner **Survey Customer** **Time** 09:15
Drainage Area **Locality/City Name** Tulsa
P.O. No **Location (No. & Name)** 2203 S 131st E Ave
Further Location Details **Inspection Level** Level 2
Outgoing Rim to Invert 10.7 ft **Outgoing Grade to Invert** 10.2 ft **Rim to Grade** 0.5 ft
Use of Sewer Sanitary **Year Laid** **Year Rehabilitated** **Media Label**
Purpose Sewer System Evaluation Survey **Sewer Category**
Pre-Cleaning No Pre-Cleaning **Date Cleaned** **Weather**
Location Code Easement/Right of Way **Potential for Runoff** **Evidence of Surcharge** Yes
Access Point Type Manhole **Coordinate System**
Northing **Easting** **Elevation** **Accuracy of GPS**
Inspection Status Remote Inspection
Additional Information No chimney
Node Surface Types

Concrete Pavement ☐ **Concrete Collar** ☐ **Asphalt** ☐ **Grass / Dirt** ☒ **Gravel** ☐ **Other** ☐

Cover

Cover Shape Circular **Cover Bearing Surface Diameter Width**
Cover Size 23.3 in **Cover Bearing Surface Diameter** 23.0 in
Civer Size Width **# Vent Holes**
Cover Material Cast Iron **Vent Hole Diameter**
Cover Frame Fit Oversized
Cover Type
☒ **Solid** ☐ **Bolted**
☐ **Vented/Slots** ☐ **Locking**
☐ **Gasketed** ☐ **Lamphole**
☐ **Hatch Single** ☐ **Inner Cover**
☐ **Hatch Double**
Cover Condition
☒ **Solid** ☐ **Missing**
☐ **Cracked** ☐ **Corroded/Pitted**
☐ **Broken** ☐ **Bolts Missing**
☐ **Restraint Missing**
☐ **Restraint Defective**

Cover Insert

Cover Insert Type None **Cover Insert Condition**
☐ **Solid** ☐ **Leaking**
☐ **Poorly Fitting** ☐ **Corroded**
☐ **Cracked/Torn/Holes** ☐ **Insert Fell**

Sheet 487

Survey Date 20250210

P.O. No

Location (No. & Name) 2203 S 131st E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Adj. Ring

Adjustment Ring Type None

Adjustment Ring Material

Adjustment Ring Height

Adjustment Ring Condition

- | | |
|----------------------------------|---|
| <input type="checkbox"/> Sound | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Leaking |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Poor Installation |

Frame

Frame Material Cast Iron

Frame Offset Distance 0.0 in

Frame Bearing Surface Width 0.8 in

Frame Depth

Frame Bearing Surface Depth 1.0 in

Frame Seal Inflow None

Frame Clear Opening Diameter 21.8 in

Frame Condition

- | | |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Cracked | <input type="checkbox"/> Corroded/Pitted/Worn |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Coated |

Frame Seal Condition

- | | |
|---|---|
| <input checked="" type="checkbox"/> Sound | <input type="checkbox"/> Loose/Not Attached |
| <input type="checkbox"/> Cracked | |
| <input type="checkbox"/> Broken | <input type="checkbox"/> Offset |

Chimney

Chimney Material 1 Other

Interior Chimney Coating/Liner None - No Coating

Chimney Material 2

Exterior Chimney Coating/Liner

Chimney Clear Opening

Chimney I/I

Chimney Depth 0.0 in

Cone

Cone Type Flattop

Cone Depth 1.5 in

Exterior Cone Coating/Liner

Cone Material Concrete (reinforced)

Interior Cone Coating/Liner

Wall

Wall Diameter 1 48

Wall Depth 10.0 in

Wall Diameter 2

Interior Wall Coating/Liner None - No Coating

Wall Material Concrete (reinforced)

Exterior Wall Coating/Liner

Bench

Bench Present Y

Bench Material Concrete (non-reinforced)

Bench Coating/Liner Bench Liner

Channel/Step**Channel**

Channel Material Concrete (reinforced)

Channel Type Concrete (reinforced)

Channel Exposure F

Channel Installed Y

Step

Steps 6

Step Material Plastic

Sheet 487

Survey Date 20250210

P.O. No

Location (No. & Name) 2203 S 131st E Ave

Inspection Level Level 2

Locality/City Name Tulsa

Inspection Status Remote Inspection

Pipe Connections

| Num | Clk Pos | Rim to Invert | Direc | Material | Shape | Diam | Width | Pipe Cond | Seal Cond | Special Condition | PSR |
|-----|----------|---------------|----------|----------|-------|------|-------|-----------|-----------|-------------------|----------------|
| 1 | 6 | 10.7 | O | VCP | C | 10 | | S | S | GR | Auto Pipe 338C |
| | Mainline | | Comments | | | | | | | | |
| 2 | 3 | 10.6 | I | VCP | C | 10 | | S | S | GR | Auto Pipe 339C |
| | Mainline | | Comments | | | | | | | | |

Observations

| Distance | Comp | Code | CD | Jnt | Stp | % | In1 | In2 | Fr | To | Video Reference |
|----------|---------|------|-------------------------|-----|-----|---|-----|-----|----|----|-----------------|
| 4.8 ft | WI | IS | | | | | | | 9 | 10 | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 6.6 ft | WI | DAR | | | | 5 | | | 9 | 10 | 360-0.0 |
| | Remarks | | On 2 steps | | | | | | | | |
| 10.1 ft | B | DSZ | | | | 5 | | | 6 | 3 | 360-0.0 |
| | Remarks | | Toilet paper and sludge | | | | | | | | |
| 10.1 ft | B | OBR | | | | 5 | | | 9 | | 360-0.0 |
| | Remarks | | | | | | | | | | |
| 10.6 ft | B | OBZ | | | | 5 | | | 6 | | 360-0.0 |
| | Remarks | | Stick | | | | | | | | |