

## 30-4076-01: Tulsa Metropolitan Utility Authority (TMUA) TMUA ES 2025-06

### Smoke Observation Summary

#### Cleanout, Defective

Address: 2921 E Dawson Rd

Basin: **CC-11**

Segment (US : DS): **030-0129:030-0128**

Intensity: **Medium**

Drainage Area (SF): **200**

Surface: **Unpaved**

Comments:

*QC Comments: retake close up showing defect, pull grass back*



#### Cleanout, Defective

Address: 2708 E Newton Pl

Basin: **CC-11**

Segment (US : DS): **030-0186:030-0185**

Intensity: **Low**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments: *Threaded collar broken*

*QC Comments: comment says threaded collar broken, take close up showing broken threaded collar, looks fine in current photo*

