

30-3676-04: Tulsa Metropolitan Utility Authority (TMUA) FY26 On-Call

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 3609 S 144th East Pl

Basin: **80-N**

Segment (US : DS): **080-0558:080-0557**

Intensity: **High**

Drainage Area (SF): **40**

Surface: **Unpaved**

Comments:

QC Comments: Take close up that shows this is a cap defect

