

30-4076-01: Tulsa Metropolitan Utility Authority (TMUA) TMUA ES 2025-06

Smoke Observation Summary

Cleanout, Defective

Address: 1214 N Sandusky Ave

Basin: **CC-TL1415C**

Segment (US : DS): **094-0461:094-0460**


Intensity: **Low**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments:

QC Comments: clarify where smoke is coming from



Cleanout, Defective

Address: 1404 N Sandusky Ave

Basin: **CC-TL1415C**

Segment (US : DS): **094-0453:094-0452**

Intensity: **Low**

Drainage Area (SF): **80**

Surface: **Unpaved**

Comments:

QC Comments: retake close up that verifies defect

