



a division of ADS Corporation

Baltimore SSO

Site Investigation Report

FM Initials: DF

Project Number: 02 Upper Jones Falls Interceptor

| | | | | | | | | |
|-----------------------------|----------------------|-----------------|-----------------|--------------|--------------------|------------|------|---|
| Site Name: | 02_JP40I | Monitor Series: | 4000 | Monitor S/N: | 1190 | Manhole #: | JP40 | Investigation Information: Upstream Input: (L/S, P/S) N/A Upstream Manhole: JP39 Downstream Manhole: JP41 Depth of Flow: 21" Description of Site Hydraulics: No abnormal conditions were observed. Manhole Information: Manhole Depth: Manhole Material/Condition: Active Drop Connections? No System Character: Residential Commercial <input checked="" type="checkbox"/> Industrial Notes: Legend: Cast Iron Flap Valve Sensor Location N.T.S.- Not to scale |
| Address / Location: | Old Cold Spring Lane | Map Page #: | 2 | Map Grid #: | 21 OO ₁ | | | |
| | | Pipe Height: | 42" | Pipe Width: | 42" | | | |
| | | IP Address: | 166.142.226.203 | | | | | |
| Access: | Drive | GPS Coords: | N DD.dddd | | W DD.dddd | | | |
| Date/Time of Investigation: | 7/22/2003 10:00 | | | | | | | |

Access Map

Plan View

Elevation

Top View

The monitoring period ended as of December 31, 2004.