

Baltimore SSO

Site Investigation Report

FM Initials: DF

Project Number: 05 Stony Run

Site Name:	05_JGF45CI	Monitor Series:	4000	Monitor S/N:	1183	Manhole #:	JGF45C	Investigation Information: Upstream Input: (L/S, P/S) N/A Upstream Manhole: JGF45B Downstream Manhole: JGF45D Depth of Flow: 7" Description of Site Hydraulics: No abnormal conditions were observed.
Address / Location:	Cold Spring Lane & Wickford Road	Map Page #:	3	Map Grid #:	29 MM ₁			
		Pipe Height:	20.875"	Pipe Width:	20.5"			
		IP Address:	166.142.228.219					
Access:	Drive	GPS Coords:	N DD.dddd 39 20.745		W DD.dddd 76 37.598			
Date/Time of Investigation:	3/24/2003 0:00							

Access Map

Plan View

Manhole Information:

Manhole Depth: 14.5"

Manhole Material /Condition:
Brick

Active Drop Connections?
No

System Character:

☐ Residential
☒ Commercial
☐ Industrial

Notes:

Elevation

Top View

Legend:

Cast Iron Flap Valve

Sensor Location

N.T.S.- Not to scale

The monitoring period ended on October 31, 2004.