



a division of ADS Corporation

Baltimore SSO

Site Investigation Report

FM Initials: DF

Project Number: 07 Greenmount Ave Interceptor

Site Name:	07_JGAA23I	Monitor Series:	4000	Monitor S/N:	1184	Manhole #:	JGAA23	Investigation Information: Upstream Input: (L/S, P/S) N/A Upstream Manhole: JGAA22 Downstream Manhole: JGAA24 Depth of Flow: 3" Description of Site Hydraulics: No abnormal conditions were observed. Manhole Information: Manhole Depth: 12' Manhole Material/Condition: Brick / Good Active Drop Connections? No System Character: <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial Notes: Legend: Cast Iron Flap Valve Sensor Location N T S - Not to scale
Address / Location:	2648 Polk Street			Map Page #:	9	Map Grid #:	43 SS	
				Pipe Height:	18"	Pipe Width:	18"	
				IP Address:	166.142.225.209			
Access:	Drive	GPS Coords:	N DD.dddd 39 19.23		W DD.dddd 76 35.6886			
Date/Time of Investigation:	3/31/2003 16:03							

The monitoring period ended as of December 31, 2004.