

Baltimore SSO

Site Investigation Report

FM Initials: DF

Project Number: 09 Gwynns Run Interceptor

Site Name:	09_130S	Monitor Series:	4000	Monitor S/N:	1206	Manhole #:	GR56	Investigation Information: Upstream Input: (L/S, P/S) N/A Upstream Manhole: GR55 Downstream Manhole: GR57 Depth of Flow: 13.25" Description of Site Hydraulics: No abnormal conditions were observed.
Address / Location:	Access road off of Carlins Park Dr	Map Page #:	7	Map Grid #:	13YY			
		Pipe Height:	22"	Pipe Width:	22"			
		IP Address:	166.143.099.122					
Access:	Drive	GPS Coords:	N DD.dddd 39 19.681	W DD.dddd 76 39.809				
Date/Time of Investigation:	7/25/2003 13:00							

Plan View

Manhole Information:

Manhole Depth: 22' 6"

Manhole Material/Condition:
Brick / Fair

Active Drop Connections?
No

System Character:
Residential
☒ Commercial
☒ Industrial

Notes:

Elevation

Top View

Legend:

Cast Iron Flap Valve

Sensor Location

N.T.S.- Not to scale

The monitoring period ended as of February 28, 2005.