





# Baltimore SSO Site Investigation Report

FM Initials: DF

Project: 14 Dead Run System Improvements

a division of ADS Corporation

Site Name:	14_16PS	Monitor Series:	4000 WR	Monitor S/N:		Manhole #:		<b>Investigation Information:</b> Upstream Input: (L/S, P/S) DNI Upstream Manhole: Downstream Manhole: Depth of Flow: 3" + - 0.38 Description of Site Hydraulics:
Address / Location:	5001 West Hills Road	Map Page #:		Map Grid #:				
		Pipe Height:	7.5"	Pipe Width:	7.5"			
Access:	Drive	IP Address:	CDPD					
		GPS Coords:	N DD.dddd		W DD.dddd			
Date/Time of Investigation:	6/29/2005 10:30							



IINFLUENT SMOOTH  
RIPPLE AT EFFLUENT PIPE LINER

## Manhole Information:

Manhole Depth: 8.5'

Manhole Material / Condition:

COATED BRICK / GOOD

Active Drop Connections?

No

System Character:

- ☒ Residential  
☐ Commercial  
☐ Industrial



Notes:

Legend:

Cast Iron Flap Valve

Sensor Location

N.T.S.- Not to scale



The monitoring period ended as of November 30, 2006.