




Baltimore SSO

Site Investigation Report


FM Initials: DF

Project Number: 15 Maiden's Choice Interceptor


Site Name:	15_MC19I	Monitor Series:	4000	Monitor S/N:	1191	Manhole #:	unknown	Investigation Information: Upstream Input: (L/S, P/S) N/A Upstream Manhole: MC18 Downstream Manhole: MC19 Depth of Flow: 7.75" Description of Site Hydraulics: No abnormal conditions were observed. Manhole Information: Manhole Depth: 12'8" Manhole Material / Condition: Brick / Good Active Drop Connections? No System Character: <input checked="" type="checkbox"/> Residential <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial Notes: Legend:  Cast Iron Flap Valve  Sensor Location N.T.S.- Not to scale
Address / Location:	South Medwick Garth and Mallow Hill		Map Page #:	11	Map Grid #:	4M		
			Pipe Height:	15"	Pipe Width:	15"		
			IP Address:	166.142.226.203				
Access:	Walk (Residential)		GPS Coords:	N DD.dddd 39 16.738		W DD.dddd 76 42.578		
Date/Time of Investigation:	4/23/03 15:00							




Access Map



Plan View



Elevation



Top View

The monitoring period ended as of March 31, 2005.