

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 206 Archwood St

Basin: **HS42**

Segment (US : DS): **347:318**


Intensity: **High**

Drainage Area (SF): **5**

Surface: **Unpaved**

Comments:

QC Comments: retake close up without smoke for verification



Cleanout, Missing/Broken Cap

Address: 310 4th St

Basin: **HS62**

Segment (US : DS): **1369:1366**

Intensity: **High**

Drainage Area (SF): **15**

Surface: **Unpaved**

Comments:

QC Comments: Missing close up photo to verify defect

