

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 107 Kate St

Basin: **HS15**

Segment (US : DS): **13132:13135**

Intensity: **High**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments:

QC Comments: retake close up without smoke and pull grass back for verification



Cleanout, Missing/Broken Cap

Address: 524 Linwood Ave

Basin: **HS62**

Segment (US : DS): **1311:1307**

Intensity: **High**

Drainage Area (SF): **15**

Surface: **Unpaved**

Comments:

QC Comments: retake close up verifying defect

