

18-4143-00: Hot Springs, AR 2025 SSES

Smoke Observation Summary

Cleanout, Defective

Address: 600 Garland Ave

Basin: **HS62**

Segment (US : DS): **1379:1378**

Intensity: **High**

Drainage Area (SF): **5**

Surface: **Unpaved**

Comments:

QC Comments: Missing close up photo to verify defect



Cleanout, Defective

Address: 720 Elkhorn Loop

Basin: **Sundance**

Segment (US : DS): **13458:13457**

Intensity: **Medium**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments: *No visual due to dog*

QC Comments: Re-attempt close up photo without smoke

