

## 30-3676-04: Tulsa Metropolitan Utility Authority (TMUA) FY26 On-Call

### Smoke Observation Summary

#### Cleanout, Missing/Broken Cap

Address: 10110 E 25th St

Basin: **83-N**

Segment (US : DS): **083-0185:083-0179**


Intensity: **High**

Drainage Area (SF): **0**

Surface: **Paved**

Comments: *Smoking area*

*QC Comments: Verify threads Add to next biweekly*



#### Cleanout, Defective

Address: 2414 S 104th East Ave

Basin: **83-N**

Segment (US : DS): **083-0218:083-0213**

Intensity: **Medium**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments: *Unable to access. No answer from homeowner and dog in backyard*

*QC Comments: Verify defect Add to next biweekly*

