

30-3676-04: Tulsa Metropolitan Utility Authority (TMUA) FY26 On-Call

Smoke Observation Summary

Cleanout, Defective

Address: 2414 S 104th East Ave

Basin: **83-N**

Segment (US : DS): **083-0218:083-0213**


Intensity: **Medium**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments: *Unable to access. No answer from homeowner and dog in backyard*

QC Comments: Verify defect



Cleanout, Defective

Address: 3132 S 133rd East Ave

Basin: **80-N**

Segment (US : DS): **080-0381:080-0380**

Intensity: **Medium**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments: *No answer dog in yard unable to verify defect*

QC Comments: reattempt access for close up if possible

