

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 1915 W 47th Pl

Basin: 40-S

Segment (US : DS): 040-0213:040-0212

Intensity: Low

Drainage Area (SF): 0

Surface: Unpaved

Comments: Used as a vent

QC Comments: Verify defect KR

