

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Missing/Broken Cap

Address: 2438 W 45th Pl S

Basin: **40-S**  
Segment (US : DS): **040-0185:040-0184**  
Intensity: **High**  
Drainage Area (SF): **50**  
Surface: **Unpaved**  
Comments: *Smoking area*  
*QC Comments: Verify threads*



Cleanout, Missing/Broken Cap

Address: 2127 W 46th Pl S

Basin: **40-S**  
Segment (US : DS): **040-0189:040-0190**  
Intensity: **High**  
Drainage Area (SF): **0**  
Surface: **Unpaved**  
Comments: *Smoking area*  
*QC Comments: Verify collar*

