

30-4107-03: Tulsa Metropolitan Utility Authority (TMUA) 2026-08 West Tulsa Phase 2 Smoke Testing

Smoke Observation Summary

Cleanout, Defective

Address: 1953 W 49th St

Basin: **40-S**

Segment (US : DS): **040-0242:040-0236**


Intensity: **Medium**

Drainage Area (SF): **200**

Surface: **Unpaved**

Comments: *Gates locked no access to get better closer pictures appears to be defective clean out*

QC Comments: try to get a closer up photo even using connecting yard and zoom in. KR



Cleanout, Defective

Address: 4433 S Santa Fe pl

Basin: **40-S**

Segment (US : DS): **040-0472:040-0471**

Intensity: **Low**

Drainage Area (SF): **0**

Surface: **Unpaved**

Comments:

QC Comments: Need close up verifying defect

